

UNITED STATES PATENT AND TRADEMARK OFFICE  
**CERTIFICATE OF CORRECTION**

PATENT NO. : 7,078,823 B2  
APPLICATION NO. : 10/787351  
DATED : July 18, 2006  
INVENTOR(S) : Blaine J. Thurgood

Page 1 of 1

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

**On the title page:**

In the section (56) titled **References Cited**

U.S. PATENT DOCUMENTS

2<sup>nd</sup> page, 1<sup>st</sup> COLUMN, 1<sup>st</sup> entry, delete "6,700,983 B1 \* 3/2004  
Bøgeskov-Jensen et al. .... 381/222"  
on the line after "6,720,666 B1 4/2004  
Lim et al."  
insert --6,740,983 B2 3/2004 Tay et al.--


**In the specification:**

COLUMN 6, LINE 6,  
COLUMN 7, LINE 55,

change "slot ends as" to --slot ends 44 as--  
change "bonding pads 34" to --bond pads  
34--

Signed and Sealed this

Thirtieth Day of October, 2007



JON W. DUDAS  
Director of the United States Patent and Trademark Office